

Inspection Photos
Location Name: DF Ranch PC GK 02-77HN
Location ID: 428119



Photo 1 – Tank Battery Sign




Photo 2 – NFPA Labels

Inspection Photos
Location Name: DF Ranch PC GK 02-77HN
Location ID: 428119



Photo 3 – Separators and ECD



Photo 4 – Wellhead

Inspection Photos
Location Name: DF Ranch PC GK 02-77HN
Location ID: 428119



Photo 5 – Wildlife Netting is in disrepair



Photo 6 – Missing Labels

Inspection Photos
Location Name: DF Ranch PC GK 02-77HN
Location ID: 428119



Photo 7 – Unused Chemical Tanks



Photo 8 – Tank Battery