

Interim Reclamation Inspection

September 13, 2022

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 332979

Inspection Document #: 697504189

Weld County, CO

SWSE Section 23 T1N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: WATTENBERG HENRY E UT B #2

Location ID: 332979



Photo 1. Photo illustrates the Operator sign.




Photo 2. Photo illustrates the Operator sign obstructed by weeds.



Inspection Photos

Location Name: WATTENBERG HENRY E UT B #2

Location ID: 332979



Photo 3. Photo taken from the well location, facing West. See comments under Photo 2.



Photo 4. Photo taken from the well location, facing Northeast. Photo illustrates unmanaged weeds and equipment in disrepair.

