

Interim Reclamation Inspection

September 13, 2022

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 318857

Inspection Document #: 697504191

Weld County, CO

SESE Section 23 T1N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: WATTENBERG, HENRY E. UNIT #C-1

Location ID: 318857



Photo 1. Photo illustrates the Operator sign.



Photo 2. Photo taken from the well location, facing East. Photo illustrates unmanaged weeds.



Inspection Photos

Location Name: WATTENBERG, HENRY E. UNIT #C-1

Location ID: 318857



Photo 3. Photo taken from the well location, facing South. See comments under Photo 2.



Photo 4. Photo taken from the well location, facing East. See comments under Photo 2.

