

# Inspection Photos

API: 071-09011

Operator: WAPITI OPERATING LLC

Inspection Date: 9/23/2022




**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09011 | Date: 9/23/2022

## Inspection Photos



**Photo 1.** There are noxious weeds along the access road that need to be controlled. The red arrow points to List B noxious weed - Houndstongue. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09011 | Date: 9/23/2022



## Inspection Photos



**Photo 2.** There are noxious weeds along the access road that need to be controlled. The red arrow points to Houndstongue which is a biennial. The leaves shown are the first year growth and is a good time for control. Previous corrective action was not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09011 | Date: 9/23/2022

## Inspection Photos



**Photo 3.** Facing northwest toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09011 | Date: 9/23/2022