



00241569

WELL SITE INSPECTION FORM

WELL NAME Cole #1API NUMBER 05 - 075 - 9198OPERATOR GibsonPERMIT NUMBER 89-212LOCATION SESW 10-9N-55WCOUNTY LoganFIELD WCINSPECTOR SP

AL/PA/DA INSPECTION RESULTS:

PASS(Y) ☒ FAIL(N) ☐ DATE 8/9/89

WELL STATUS:

FN ☐ FD ☐ WO ☐

=====

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____

CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____

RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____

DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____

TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____

SKIM PIT: _____ gal TANKS: () _____ bbls

EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____

METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____

HOLE PLUGGED: YES ☒ NO ☐ PITS BACKFILLED: YES ☒ NO ☐MATERIAL BURIED: YES ☒ NO ☐ NA _____ SITE CLEAN: YES ☒ NO ☐BOND RELEASE OK: YES ☒ NO ☐ FED _____ HOLE MARKER: YES ☐ NO ☐

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS _____

