



RM

99999999

Well Name COLE #1 API Number 05 075-9198
 Operator J.W. GIBSON Permit # 89-212
 Location SESWID-9N-55W County LOGAN
 Field WC Inspector R. T. Slick

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) ☒ Fail(N) ☐ Date 11/6-90 ND ☐ DG ☐ WO ☐ PR ☐ SI ☐ TA ☐

=====

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
 Consistent with APD casing Program? YES ☐ NO ☐ Returns _____
 Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
 Drilling Pits: Closed ☐ Open ☐ Wellhead Installed: _____ Sign: Yes ☐ No ☐
 Tank ID: Yes ☐ No ☐ N/A ☐ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
 Equipment _____ Meter Run: Yes ☐ No ☐
 Bradenhead Press: _____ Fluid: No ☐ Yes ☐ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: 4-7-89 Date Permit Expired: _____
 Hole Plugged: Yes ☒ No ☐ Pits Backfilled: Yes ☒ No ☐
 Material Buried: Yes ☒ No ☐ N/A ☐ Site Clean: Yes ☒ No ☐
 Bond Release OK: Yes ☒ No ☐ Fed ☐ Hole Marker: Yes ☐ No ☒

Date of Safety/Status Inspection _____

Comments: _____

Violations: Yes ☐ No ☒ Date Sent: _____



00241563