

Inspection Photos

September 26, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 324234

Location Name: McBurney-67S91W /12SENE

Inspection Document #: 702800734

Garfield County, CO

SENE Section 12 T7S R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McBurney-67S91W /12SENE
Location ID: 324234



Photo 1. Photo taken from the south shows an overview of the reclaimed Location.



Photo 2. Photo taken from the southwest show a portion of the Location where perennial establishment is low and bare ground is common.

Inspection Photos
Location Name: McBurney-67S91W /12SENE
Location ID: 324234



Photo 3. Photo shows an example of bull thistle (List B Noxious) found occasionally throughout the Location.



Photo 4. Photo shows an example of plumeless thistle (List B Noxious) found occasionally throughout the Location.

Inspection Photos
Location Name: McBurney-67S91W /12SENE
Location ID: 324234



Photo 5. Photo shows an example of Canada thistle (List B Noxious) and mullein (List C Noxious) found occasionally throughout the Location.



Photo 6. Photo taken from the north of the Location shows a portion of the Location without perennial establishment and dominated by annual weeds, including cheatgrass (List C Noxious).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800734

Inspection Photos
Location Name: McBurney-67S91W /12SENE
Location ID: 324234



Photo 7. Photo shows an example of an area of the Location where perennial species are well established.



Photo 8. Photo shows an example of an area of the Location where yellow sweet clover, a biennial dominates. Perennial species are established but fairly sparse.

Inspection Photos
Location Name: McBurney-67S91W /12SENE
Location ID: 324234




Photo 9. Photos taken to the east and north of the Location show examples of reference area vegetation.