



Inspection Photos
Spill/Release Name: Long Ridge J15
Spill/Release ID: 474500
Remediation Project #15535
Inspection Date: August 25, 2022

**Overview of the “pumping system”
associated with Remediation
Project #15535.**



Inspection Photos
Spill/Release Name: Long Ridge J15
Spill/Release ID: 474500
Remediation Project #15535
Inspection Date: August 25, 2022

Overview of the “pumping system”
associated with Remediation
Project #15535.

Aug 25, 2022 12:48:55
+39.6098N -108.038





Inspection Photos
Spill/Release Name: Long Ridge J15
Spill/Release ID: 474500
Remediation Project #15535
Inspection Date: August 25, 2022

Overview of the “pumping system”
associated with Remediation
Project #15535.





Inspection Photos
Spill/Release Name: Long Ridge J15
Spill/Release ID: 474500
Remediation Project #15535
Inspection Date: August 25, 2022

Unlabeled steel AST.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Aug 25, 2022 12:45:59
+39.6098N -108.038

Inspection Photos
Spill/Release Name: Long Ridge J15
Spill/Release ID: 474500
Remediation Project #15535
Inspection Date: August 25, 2022

Unlabeled steel AST.

