

Inspection Photos
Location Name: Lajco 4N67W 17M Pad
Location ID: 443320



Colorado Oil & Gas Conservation Commission
40.31972, -104.91342, 1448.2m, 118°
09/29/2022 11:42:36


Production facility



Colorado Oil & Gas Conservation Commission
40.31952, -104.91382, 1446.3m, 216°
09/29/2022 11:43:21

Wellheads

Inspection Photos
Location Name: Lajco 4N67W 17M Pad
Location ID: 443320



Colorado Oil & Gas Conservation Commission
40.32481, -104.90768, 291°
09/29/2022 12:11:49

Wellhead



Colorado Oil & Gas Conservation Commission
40.31929, -104.91383, 1446.9m, 337°
09/29/2022 12:12:15

Lubricator outlet leak

Inspection Photos
Location Name: Lajco 4N67W 17M Pad
Location ID: 443320



Trash



Unused equipment

Inspection Photos
Location Name: Lajco 4N67W 17M Pad
Location ID: 443320



Colorado Oil & Gas Conservation Commission
40.31977, -104.91384, 1447.3m, 310°
09/29/2022 12:05:56

Unused equipment




Colorado Oil & Gas Conservation Commission
40.31995, -104.91329, 1449.2m, 68°
09/29/2022 12:06:44

Unused equipment

Inspection Photos
Location Name: Lajco 4N67W 17M Pad
Location ID: 443320



Unused equipment



Unused equipment