

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/27/2022

Submitted Date:

09/29/2022

Document Number:

689501410

FIELD INSPECTION FORM
 Loc ID 432240 Inspector Name: Brown, Kari On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 1801 CALIFORNIA STREET #2500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
482710	SPILL OR RELEASE	AC	09/14/2022		-	Qualls Separator	EI

General Comment:

This is an environmental inspection of Spill ID 482710 reported 8/19/2022. Any corrective actions from previous inspections that have not been addressed are still applicable.

Photo attached to document site conditions.

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: _____

Comment: Excavation was open at separators to a depth of ~3'. No impacts were visible in situ. No groundwater was observed in the open excavation.

Corrective Action: Pursuant to Rule 912.b.(6) Operator is required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate that the Spill or Release has been fully cleaned up and complies with Table 915-1; or A Form 27 if any of the criteria listed in Rules 912.b.(6).B.i-iii apply. If Remediation will continue under an approved Form 27, the Operator will also submit a Form 19 – Supplemental which requests closure of the Spill or Release and includes the Remediation project number assigned by the Director.

Date: 11/19/2022

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Adequate		
Comment		Impacted soil had been place on a tarp and was in the process of being removed from location.		
Corrective Action				Date: _____

Spill/Remediation:

Comment: _____

Corrective Action: _____

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689501411	Impacted Soil	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874119
689501412	Open Excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874120