

Inspection Photos
Location Name: Dreiling 27N-32HZ
Location ID: 434988



Photo 1 WH sign.

Photo 2 WH

Inspection Photos
Location Name: Dreiling 27N-32HZ
Location ID: 434988



Photo 3 Pump Jack.

Photo 4 Ancillary equip.

Inspection Photos
Location Name: Dreiling 27N-32HZ
Location ID: 434988



Photo 5 LACT.

Photo 6 TB signs.



Inspection Photos
Location Name: Dreiling 27N-32HZ
Location ID: 434988



Photo 7 TB.

Photo 8 VRU.



Inspection Photos
Location Name: Dreiling 27N-32HZ
Location ID: 434988



Photo 9 ancillary equip..

Photo 10 HHS.



Inspection Photos
Location Name: Dreiling 27N-32HZ
Location ID: 434988



Photo 11 Compressor.

Photo 12 ECD.



Inspection Photos
Location Name: Dreiling 27N-32HZ
Location ID: 434988



Photo 13 VRT.

Photo 14 Gas Meter Runs.