

**Inspection Photos**  
**Location Name: Candelaria 33-5 10-1**  
**Location ID: 378719**



**IMG 01**  
**Well sign**



**IMG 02**  
**Location overview**





**IMG 03**  
**Impacted material**



**IMG 04**  
**Belt guard**



**IMG 05**  
**Transducer, gauge, and other equipment**



**IMG 06**  
**Sign**





**IMG 07**  
**Unused enclosure**