



WELL SITE INSPECTION FORM

99999999

#1

Well Name Arford API Number 05 - 075 - 6309
Operator Gulf Oil Corp Permit # 11111
Location SWNE 28-9N-54W County Logan
Field Arford Inspector DAB
AL/PA/DA Inspection Results: Well Status:
Pass (Y) ☒ Fail (N) ☐ Date 8/2/90 FN ☐ FD ☐ WO ☐ PR ☐ SI ☐

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
Consistent with APD casing Program? YES ☐ NO ☐ Returns _____
Rig _____ BOP'S _____ Contact _____

Date of Inspection Before/During/After Completion _____

Prod. Csg. Set? _____ Completion Rig/Activity _____
Drilling Pits: Closed ☐ Open ☐ Wellhead Installed: _____ Sign: Yes ☐ No ☐
Tank ID: Yes ☐ No ☐ N/A ☐ Skim Tank/Pit: _____ Prod. Tanks: () _____ BBLs
Equipment _____ Meter Run: Yes ☐ No ☐
Bradenhead Press: _____ Fluid: No ☐ Yes ☐ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: 1951 Date Permit Expired: _____
Hole Plugged: Yes ☐ No ☒ Pits Backfilled: Yes ☒ No ☐
Material Buried: Yes ☐ No ☒ N/A ☐ Site Clean: Yes ☒ No ☐
Bond Release OK: Yes ☐ No ☐ Fed ☐ Hole Marker: Yes ☒ No ☐

Date of Safety/Status Inspection 8/2/90

Comments: There is a 4 inch diameter iron rod sticking
up about 6 ft into the air (No cap)
Depends on if rancher wants to use it
for a cattle scratch. (Rangeland for cattle)



00238395

Violations: Yes ☐ No ☐ Notice Sent: Yes ☐ No ☐ Date Sent: _____