

Inspection Photos

September 15, 2022

Operator: KP Kauffman Company Inc - #46290

Location ID: 450973

Location Name: Walden Land Treatment Facility /T7-P18

Inspection Document #: 702800736

Jackson County, CO

NENE Section 18 T9N R78W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Walden Land Treatment Facility /T7-P18

Location ID: 450973



Photo 1. Photo taken from the northwest of the Location shows drill cuttings.



Photo 2. Refer to Photo 1 comment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800736

Inspection Photos
Location Name: Walden Land Treatment Facility /T7-P18
Location ID: 450973



Photo 3. Photo taken from the northwest of the Location shows sediment migrating offsite from the drill cuttings management area through the eroded perimeter berm.



Photo 4. Refer to Photo 3 comment.

Inspection Photos
Location Name: Walden Land Treatment Facility /T7-P18
Location ID: 450973



Photo 5. Photo taken from the northwest of the Location shows erosion occurring at the perimeter berm.



Photo 6. Refer to Photo 5 comment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800736