

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT-66S91W /31NWNE

Location ID: 335276



Network: Sep 27, 2022 at 12:50:56 PM MD
Local: Sep 27, 2022 at 12:50:56 PM MD

Photo #7804 From entrance to location.



Network: Sep 27, 2022 at 12:51:01 PM MD
Local: Sep 27, 2022 at 12:51:01 PM MD

Photo #7805 From entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT-66S91W /31NWNE

Location ID: 335276



Photo #7806 From entrance to location.



Photo #7807 Unused equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT-66S91W /31NWNE

Location ID: 335276



Photo #7808 Unused equipment.



Photo #7809 Unused equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GIBSON GULCH UNIT-66S91W /31NWNE

Location ID: 335276



Photo #7810 Unused equipment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources