

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GGU VAN ORDSTRAND-66S91W /30NESW

Location ID: 335467



**Photo #7817** From entrance to location.



**Photo #7818** From entrance to location.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GGU VAN ORDSTRAND-66S91W /30NESW

Location ID: 335467



**Photo #7822 Unused equipment.**



**Photo #7922 Unused equipment and undesirable plant species.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GGU VAN ORDSTRAND-66S91W /30NESW

Location ID: 335467



**Photo #7824 Undesirable plant species.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources