

# Final Reclamation and Stormwater Inspection

Date: 09/22/2022

Operator: GREAT WESTERN OPERATING COMPANY  
LLC - 10110

Location ID: 320492

Inspection Document #: 696105458

Adams County, CO

SWSE Section 9 T1S R67W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: EQUINOX #15-9  
Location ID: 320492



**Photo 1.** Taken south of location, facing northeast. Photo illustrates that location appears to have been reclaimed with no visible oil and gas equipment, and access road and location regraded to reflect reference areas, which is now a golf course within a sub-development.



Inspection Photos  
Location Name: EQUINOX #15-9  
Location ID: 320492



**Photo 2.** Taken from northeast portion, facing southwest. Annual weedy vegetation outlined in red (russian thistle).



Inspection Photos  
Location Name: EQUINOX #15-9  
Location ID: 320492



**Photo 3.** Facing southeast, see comments in photo 2.



Inspection Photos  
Location Name: EQUINOX #15-9  
Location ID: 320492



**Photo 4.** Facing northeast. Canada Thistle (CO List B Noxious Weed) outlined in red.



Inspection Photos  
Location Name: EQUINOX #15-9  
Location ID: 320492



**Photo 5.** Close up photo of Canada Thistle.



Inspection Photos  
Location Name: EQUINOX #15-9  
Location ID: 320492



**Photo 6.** Reference area photo taken west of location, facing northwest. Reference area is predominantly crested wheat grass.