

Final Reclamation and Stormwater Inspection

Date: 09/22/2022

Operator: GREAT WESTERN OPERATING COMPANY -
10110

Location ID: 320486

Inspection Document #: 696105460

Adams County, CO

NWNW Section 16 T1S R67W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name:HRS STATE #6-16
Location ID: 320486



Photo 1. Taken west of location, facing east. Photo illustrates that some reclamation work has been conducted with evidence of western wheatgrass in drill rows. Also pictured are some areas of bare soil and annual weedy vegetation, e.g. russian thistle.

Inspection Photos
Location Name:HRS STATE #6-16
Location ID: 320486



Photo 2. Taken west of location, facing east. Photo illustrates access road that does not appear to have been reclaimed (visible crown to the road) and annual weedy vegetation, e.g. russian thistle.



Photo 3. Close up photo taken of access road, illustrating the presence of gravel.

Inspection Photos
Location Name:HRS STATE #6-16
Location ID: 320486



Photo 4. Taken from northwestern portion of location, facing east. Photo illustrates some revegetation efforts have been conducted as evidenced by drill rows. Variable vegetation height possibly a result of compaction issues.

Inspection Photos
Location Name:HRS STATE #6-16
Location ID: 320486



Photo 5. Facing west, see comments in photo 4.

Inspection Photos
Location Name:HRS STATE #6-16
Location ID: 320486



Photo 6. Taken from western portion of location, facing southwest. Photo illustrates presence of gravel and areas of non-uniform vegetation cover possibly resulting from compaction issues.

Inspection Photos
Location Name:HRS STATE #6-16
Location ID: 320486



Photo 7. Taken from eastern portion of location, facing south. Photo illustrates debris and annual weedy vegetation, predominantly russian thistle.

Inspection Photos
Location Name:HRS STATE #6-16
Location ID: 320486



Photo 8. Taken from eastern portion of location, facing south. Photo illustrates annual weedy vegetation, predominantly russian thistle.

Inspection Photos
Location Name:HRS STATE #6-16
Location ID: 320486



Photo 9. Taken from southeastern portion of location, facing west. Photo illustrates areas of non-uniform vegetation cover resulting in bare soil, possibly a result of compaction issues. Also pictured, annual weedy vegetation.