

# Final Reclamation and Stormwater Inspection

Date: 09/22/2022

Operator: GREAT WESTERN OPERATING COMPANY LLC - 10110

Location ID: 320446

Inspection Document #: 696105461

Adams County, CO

SWSW Section 9 T1S R67W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: JOHN H EHLER "A" #1  
Location ID: 320446



**Photo 1.** Taken northwest of location, facing south. Debris observed on location (outlined in red) that needs to be properly disposed of.



Inspection Photos  
Location Name: JOHN H EHLER "A" #1  
Location ID: 320446



**Photo 2.** Taken near well location, facing southeast. Red outline illustrates weedy annual vegetation (russian thistle).



Inspection Photos  
Location Name: JOHN H EHLER "A" #1  
Location ID: 320446



**Photo 3.** Close up photo of well location, facing southeast. Photo illustrates weedy annual vegetation (russian thistle) and subsidence, approximately 6" below surface grade (outlined in red).



Inspection Photos  
Location Name: JOHN H EHLER "A" #1  
Location ID: 320446



**Photo 4.** Taken west of location, facing northeast. Photo illustrates approximate access road location that appears to have been reclaimed and is reflective of reference areas.