

Interim Reclamation and Stormwater Inspection

Date: 09/22/2022

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 320547

Inspection Document #: 696105465

Adams County, CO

SESE Section 1 T1S R68W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Morrison #16-1
Location ID: 320547



Photo 1. Taken from northern end of location, facing south. Photo illustrates unused equipment throughout the location.

Inspection Photos
Location Name: Morrison #16-1
Location ID: 320547



Photo 2. Close up photo of pump jack equipment. Alfalfa growing up through equipment indicates it has been stored and unused for a period of time.

Inspection Photos
Location Name: Morrison #16-1
Location ID: 320547



Photo 3. Taken from southeastern portion of location, facing west. Photo illustrates unused equipment and annual weedy vegetation (russian thistle) highlighted in red arrows.

Inspection Photos
Location Name: Morrison #16-1
Location ID: 320547



Photo 4. Taken from southwest portion of location, facing northwest. See comments in photo 3. Red arrow indicates wellhead sign in a pile of pipe fencing. This sign should be located at the wellhead.

Inspection Photos
Location Name: Morrison #16-1
Location ID: 320547



Photo 5. Close up photo of wellhead sign attached to pipe fencing, see comments in photo 4.

Inspection Photos
Location Name: Morrison #16-1
Location ID: 320547



Photo 6. Close up photo of unused equipment.

Inspection Photos
Location Name: Morrison #16-1
Location ID: 320547



Photo 7. Facing west, see comments in photo 6.

Inspection Photos
Location Name: Morrison #16-1
Location ID: 320547



Photo 8. Facing east, see comments in photo 6.

Inspection Photos
Location Name: Morrison #16-1
Location ID: 320547



Photo 9. Facing southeast, see comments in photo 6.