



Response to: APACHE 33B-20, API #: 043-06157, Insp. #:695106759 (on photos)
Insp Doc #:695106760



REMOVE VEGETATION FROM INSIDE TANK BATTERY
CONTAINMENT PER RULE 606. CA DATE 10-3-2022

-Operator completed task 9/21/22 (was in progress at time of Inspection).



Install battery sign to comply with Rule 605.e (separate battery sign is required for wells servicing battery).
THIS IS SECOND NOTICE OF THIS CORRECTIVE ACTION. IMMEDIATE ACTION IS REQUIRED.

-Operator installed tank battery sign the following day, 9/28/22.

Placards for Crude and NFPA, but contents not spelled out.

-Operator labeled tanks with respective well names, and confirmed content, volume and correct labeling on 9/28/22.