


WEEDS AROUND WELLHEAD AND PUMPJACK. CA: REMOVE WEEDS PER RULE 606.

-Removed all weeds around pumpjack and surrounding area



Continued.....

Response to: FIR Doc#695106762, Loc Id: 417859 Name: Woolly Bugger 34-20

IMPACTED MATERIAL/STAINED SOIL AROUND WELLHEAD FROM LEAKS AND/OR EXCESSIVE ROD OIL USE. CA: CLEAN UP PER RULE 1002.f2(c)

-Cleaned wellhead; Removed and disposed impacted soil and replaced with clean soil.

