

Location

Overall Good:

| Signs/Marker: | | | |
|----------------------|---|-------|------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | 500 BBL Water Tank - NFPA and Capacity Labels. See photos | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 10/28/2022 |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good:

| Spills: | | | |
|----------------|------|--------|--|
| Type | Area | Volume | |
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

| Fencing/: | | | |
|--------------------|-------------------|-------|--|
| Type | LOCATION | | |
| Comment: | Barbed Wire Fence | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | Panels | | |
| Corrective Action: | | Date: | |

| Equipment: | | | corrective date |
|-------------------------------|----------------------------------|-------|-----------------|
| Type: Vertical Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heater Treater | # 1 | | |

| | | | |
|---------------------|-----|--|-------|
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | 500 BBLs | FIBERGLASS AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | Shares berm with the Crude Oil Tanks | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | 100 BBLs | PBV FIBERGLASS | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | Shares berm with the Crude Oil Tanks | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 500 BBLs | STEEL AST | | 40.888220,-104.165460 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|-----------|----------|--|
| Condition | Adequate | |
|-----------|----------|--|

| | |
|------------------|--|
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| Yes/No | NO | | |
|--------------------|----|--|-------|
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 418169 Type: WELL API Number: 123-31844 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | Gravel | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| Routine Field Inspection. Water Tank Labels | petrie | 09/27/2022 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403179145 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5870989 |
| 696304480 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5870987 |