

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2022

Submitted Date:

10/04/2022

Document Number:

690010190

**FIELD INSPECTION FORM**Loc ID 459798 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

1 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459796	WELL	XX	12/12/2018		123-49042	Shelton H03-615	ND
459797	WELL	XX	12/12/2018		123-49043	Shelton H01-783	ND
459799	WELL	XX	12/12/2018		123-49044	Shelton H13-768	ND
459800	WELL	XX	12/12/2018		123-49045	Shelton H01-780	ND
459801	WELL	XX	12/12/2018		123-49046	Shelton H03-625	ND
459802	WELL	XX	12/12/2018		123-49047	Shelton H13-782	ND
459803	WELL	XX	12/12/2018		123-49048	Shelton H13-773	ND

**General Comment:**

**Inspected Facilities**

Facility ID: <u>459796</u>	Type: <u>WELL</u>	API Number: <u>123-49042</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459797</u>	Type: <u>WELL</u>	API Number: <u>123-49043</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459799</u>	Type: <u>WELL</u>	API Number: <u>123-49044</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459800</u>	Type: <u>WELL</u>	API Number: <u>123-49045</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459801</u>	Type: <u>WELL</u>	API Number: <u>123-49046</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459802</u>	Type: <u>WELL</u>	API Number: <u>123-49047</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459803</u>	Type: <u>WELL</u>	API Number: <u>123-49048</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>

**COGCC Comments**

Comment	User	Date
Wells on location are AP status. No surface disturbance observed at time of inspection. Survey stakes in the area.	carlilec	10/04/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690010191	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877134">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877134</a>