

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SCOTT-66S92W /25SWSE

Location ID: 335079



Photo #7881 From entrance to location.



Photo #7882 From entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SCOTT-66S92W /25SWSE

Location ID: 335079



Photo #7883 From entrance to location.



Photo #7884 Unused equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SCOTT-66S92W /25SWSE

Location ID: 335079



Photo #7885 Unused equipment.




Photo #7886 Unused equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SCOTT-66S92W /25SWSE

Location ID: 335079



Photo #7889 Unused equipment.



Photo #7888 Loadline open ended.