

**Inspection Photos**  
**Location Name: Speaker 27-8-6 PAD**  
**Location ID: 434772**



**Photo 1 – Pumping Units**



**Photo 2 – Flare**

**Inspection Photos**  
**Location Name: Speaker 27-8-6 PAD**  
**Location ID: 434772**



**Photo 3 – ECDs and Heater Treater**



**Photo 4 – Tank Battery**



**Inspection Photos**  
**Location Name: Speaker 27-8-6 PAD**  
**Location ID: 434772**



**Photo 5 – Tank Battery Sign**



**Photo 6 – Gas Meter Shed**



**Inspection Photos**  
**Location Name: Speaker 27-8-6 PAD**  
**Location ID: 434772**

Station ID #		Lease Name		BLS	
Sensor Serial #		Tube Serial #		Federal/State ID#	
RTU Serial #	RTU Brand	Section	Township	Range	
SP Range	Temp Range	Meter Brand	Contract Hour	Volume Calculation Method	Tap Location
1500				Delta	Upstream/Downstream
DP Range	Pipe ID	Atm Pressure	Pressure Base		
800					
Date	Cal SP Span	Cal DP Span	Orifice Bore	Beta Ratio	Specific Gravity
				.1633	
				.11	
				.1	
6/15/18	0-300	0-300	.625	.1633	.8345
7/20/18	0-300	0-300	.625	.1633	.8345
8/29/18	0-300	0-300	.625	.1633	.8345
9/24/18	300	300	.625	.1633	.8345
6/23/21	300	300	.625	.1633	.8345
6/21/21	300	300	.625	.1633	.8345

Colorado Oil and Gas Conservation Commission  
 40.6396, -104.20004, 4729.5ft, 271°  
 09/27/2022 13:55:38

**Photo 7 – Gas Meter Calibration Card**



**Photo 6 – West Heater Treaters**

**Inspection Photos**  
**Location Name: Speaker 27-8-6 PAD**  
**Location ID: 434772**



**Photo 9 – Weeds in the Interim Reclamation Area**



**Photo 10 – Weeds in the Interim Reclamation Area**



**Inspection Photos**  
**Location Name: Speaker 27-8-6 PAD**  
**Location ID: 434772**



**Photo 11 – Weeds in the Interim Reclamation Area**