

Inspection Photos
Location Name: Speaker 1-27-31-8-61 PAD
Location ID: 424603



Photo 1 – Wellheads



Photo 2 – Tank Battery

Inspection Photos

Location Name: Speaker 1-27-31-8-61 PAD

Location ID: 424603



Photo 3 – ECD and Heater Treater



Photo 4 – Flare

Inspection Photos
Location Name: Speaker 1-27-31-8-61 PAD
Location ID: 424603



Photo 5 – Separator and Gas Meter Sheds




Photo 6 – Gas Meter Calibration Card

Inspection Photos
Location Name: Speaker 1-27-31-8-61 PAD
Location ID: 424603



Photo 7 – Gas Lift Injection Meter Shed and Compressor



Photo 6 – Compressor Day Tanks

Inspection Photos
Location Name: Speaker 1-27-31-8-61 PAD
Location ID: 424603



Photo 9 – Weeds in the Interim Reclamation Area



Photo 10 – Weeds in the Interim Reclamation Area

Inspection Photos
Location Name: Speaker 1-27-31-8-61 PAD
Location ID: 424603



Photo 11 – Weeds in the Interim Reclamation Area