

# Final Reclamation and Stormwater Inspection

Date: 09/22/2022

Operator: BATES\* JAMES EDWARD - 6575

Location ID: 319816

Inspection Document #: 696105462

Adams County, CO

NWSE Section 7 T1S R67W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: WIERMAN #2  
Location ID: 319816



**Photo 1.** Historical imagery taken circa 1963. Red arrow indicates approximate well location. Minimal disturbance documented from this photo.

Inspection Photos  
Location Name: WIERMAN #2  
Location ID: 319816



**Photo 2.** Historical imagery taken circa 1972. See comments in photo 1.

Inspection Photos  
Location Name: WIERMAN #2  
Location ID: 319816



**Photo 3.** Historical imagery taken circa 1975. Image illustrates oil and gas operations under construction based on spud and completion dates (01/09/1975 and 05/26/1975, respectively) from scout card with larger surface disturbance. Red arrow indicates approximate well location.

Inspection Photos  
Location Name: WIERMAN #2  
Location ID: 319816



**Photo 4.** Google Earth imagery from circa 2021 illustrates surface disturbance, outlined in red polygon.

Inspection Photos  
Location Name: WIERMAN #2  
Location ID: 319816



**Photo 5.** Taken south of location, facing north. Photo illustrates reference area (e.g. wheat stubble).

Inspection Photos  
Location Name: WIERMAN #2  
Location ID: 319816



**Photo 6.** Taken near well location, facing north. Photo illustrates non-uniform vegetation cover resulting in bare soil and annual weedy vegetation observed, e.g. russian thistle and kochia.

Inspection Photos  
Location Name: WIERMAN #2  
Location ID: 319816



**Photo 7.** Taken from eastern portion of location, facing northwest. See comments in photo 6.

Inspection Photos  
Location Name: WIERMAN #2  
Location ID: 319816



**Photo 8.** Taken east of location and south of former access road, facing north. Photo illustrates access road appears to meet final reclamation standards and is reflective of reference area crop, e.g. wheat stubble).