

Final Reclamation and Stormwater Inspection

Date: 09/22/2022

Operator: EXTRACTION OIL AND GAS INC - 10459

Location ID: 414507

Inspection Document #: 696105468

Adams County, CO

NESE Section 3 T1S R68W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: LARKRIDGE MA (MULTIWELL)

03-09D

Location ID: 414507



Photo 1. Taken from eastern portion, facing west. It appears operator has performed final reclamation activities with evidence of drill rows and desirable vegetation observed.

Inspection Photos

Location Name: LARKRIDGE MA (MULTIWELL)

03-09D

Location ID: 414507



Photo 2. Taken from eastern location, facing south. See comments in photo 1.

Inspection Photos

Location Name: LARKRIDGE MA (MULTIWELL)

03-09D

Location ID: 414507



Photo 3. Taken from eastern portion, facing west. Non-uniform vegetation cover and annual weedy vegetation (russian thistle) observed during inspection, outlined in red.



Inspection Photos

Location Name: LARKRIDGE MA (MULTIWELL)

03-09D

Location ID: 414507



Photo 4. Taken from southeastern portion, facing west. See comments in photo 1.



Inspection Photos

Location Name: LARKRIDGE MA (MULTIWELL)

03-09D

Location ID: 414507



Photo 5. Taken from southwestern portion, facing northeast. See comments in photo 1.