

Inspection Photos

September 27, 2022

Operator: Matrix Oil Corporation - #10402

Location ID: 428755

Location Name: Sheridan /11-2

Inspection Document #: 702800755

Rio Blanco County, CO

TR 47A Section 11 T1N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Sheridan /11-2
Location ID: 428755



Photo 1. Photo taken from the southeast shows an overview of the southern portion of the Location. Note soil stockpile, cut slope, access road and tank remain. Final Reclamation has not been performed.



Photo 2. Photo taken from the southeast shows an overview of the northern portion of the Location.



Inspection Photos
Location Name: Sheridan /11-2
Location ID: 428755



Photo 3. Photo taken from the center of the Location shows equipment remaining on Location including the pump jack, pipes/tubing and tanks.



Photo 4. Photo taken from the southeast shows an example of multiple tanks present on Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800755

Inspection Photos
Location Name: Sheridan /11-2
Location ID: 428755



Photo 5. Photo taken from the north of the Location shows equipment remaining.



Photo 6. Photo taken from the north of the Location shows equipment remaining. Note also the eroding cut slope (right) and flat pad (left). The Location must be recontoured to fit with the surrounding landscape.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800755

Inspection Photos
Location Name: Sheridan /11-2
Location ID: 428755



Photo 7. Photo taken from the west of the Location shows equipment/debris remaining. Note also the eroding cut slope and flat pad.



Photo 8. Photo taken from the west of the Location shows equipment/debris remaining. Note also the eroding cut slope and flat pad.



Inspection Photos
Location Name: Sheridan /11-2
Location ID: 428755



Photo 9. Photo taken from the west shows the eroded cut slope. Note undermining and exposed roots (red arrow).



Photo 10. Photo taken from the west shows the eroded cut slope.

Inspection Photos
Location Name: Sheridan /11-2
Location ID: 428755



Photo 11. Photo taken from the northwest shows the eroding cut slope.



Inspection Photos
Location Name: Sheridan /11-2
Location ID: 428755



Photo 12. Photo taken from the southeast shows the access road culvert remains.



Photo 13. Photo taken from the southeast of the Location shows the transition from the fill slope to an adjacent field below; Location has not been contoured to fit the surrounding landscape. Note also access road remaining (left).

