

Inspection Photos

September 28, 2022

Operator: Lyster Oil Company Inc - #51922

Location ID: 399184

Location Name: Mcdermott-Federal (Gov)-66N86W /24SESE

Inspection Document #: 702800757

Routt County, CO

SESE Section 24 T6N R86W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McDermott-Federal (GOV)-66N86W /24SESE
Location ID: 399184



Photo 1. Photo from the 8/1/22 inspection showing a buried pipe coming out of the fill slope at the west of the Location, with approximate coordinates.



Photo 2. Photo from the 9/28/22 inspection showing the same buried pipe pictured in Photo 1 remaining in the fill slope at the west of the Location. Note approximate coordinates for location and removal of pipe.

Inspection Photos
Location Name: McDermott-Federal (GOV)-66N86W /24SESE
Location ID: 399184



Photo 3. Photo taken directly adjacent to the pipe in Photo 2 shows a cable remaining in the fill slope at the west of the Location.



Inspection Photos

Location Name: McDermott-Federal (GOV)-66N86W /24SESE

Location ID: 399184



Photo 4. Photo taken from the well marker shows pipe debris found throughout the Location. Inspector piled debris for removal.



Photo 5. Photo taken from the west of the Location shows where a buried pipe appears to have been removed.