

Inspection Photos

September 28, 2022

Operator: Beeman Oil & Gas Inc - #7125

Location ID: 474134

Facility ID: 475041, 477783

Location Name: Grassy Creek Coal #1

Inspection Document #: 702800764

Routt County, CO

NWNE Section 35 T6N R87W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Grassy Creek Coal #1
Facility ID: 475041, 477783



Photo 1. Photo taken from the west shows an overview of the Location.



Inspection Photos
Location Name: Grassy Creek Coal #1
Facility ID: 475041, 477783



Photo 2. Photo shows the easternmost tank at the Location operated by Beeman lacking proper labeling.



Photo 3. Refer to Photo 2 comment.



Inspection Photos
Location Name: Grassy Creek Coal #1
Facility ID: 475041, 477783



Photo 4. Photo shows stained soil within the tank secondary containment.



Photo 5. Photo shows where the contents of a tank appears to be weeping from the side of the tank.

Inspection Photos
Location Name: Grassy Creek Coal #1
Facility ID: 475041, 477783



Photo 6. Photo shows stained soil beneath a tank valve



Photo 7. Photo shows stained soil beneath a load line pipe.

Inspection Photos
Location Name: Grassy Creek Coal #1
Facility ID: 475041, 477783



Photo 8. Photos show erosion occurring on the access road at the west of the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702800764