

Inspection Photos and Issue Report

9/29/2022

Operator: TEP ROCKY MOUNTAIN LLC #
96850

Location #436652
Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location #436652



September 29, 2022



September 29, 2022

Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east. Photos also show vegetation on the Location is predominantly Undesirable and Weedy Plant species such as Russian thistle and Halogeton. Though desirable plant establishment was observed, perennial revegetation is sparse throughout the Location and not uniform.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location #436652



September 29, 2022



September 29, 2022

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location #436652



September 29, 2022

Photo 3: Photo example showing areas where desirable plant establishment was observed, however perennial revegetation is sparse throughout the Location and not uniform. Location predominantly Undesirable Plant Species.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location #436652



September 29, 2022



September 29, 2022

Photo 4: Photo example showing access roads. Compaction concerns appear to remain; desirable plant establishment is not progressing towards 1004 standards. Vegetation observed on road predominantly Russian thistle and Halogeton.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources