

# Inspection Photos and Issue Report

9/29/2022

Operator: TEP ROCKY MOUNTAIN LLC #  
96850

Location #433287  
Rio Blanco County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850  
Location #433287



**Photo 1:** Photos 1-2 taken from the southeast end of the production areas. Photos provide an overview of the Location from southwest, west, north to northeast.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850  
Location #433287



September 29, 2022



September 29, 2022

**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850  
Location #433287



September 29, 2022



September 29, 2022

**Photo 3:** Photo example showing reclamation on the interim areas.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850  
Location #433287



**Photo 4:** Photo example showing BMPs remain missing or insufficient on the cut slopes of the Location; erosion degradation apparent.

