

Inspection Photos
Location Name: Cass 11-9H
Location ID: 420717



Photo 1 – ECD and Gas Meter – Weeds

Photo 2 – Heater Treater – Weeds

Inspection Photos
Location Name: Cass 11-9H
Location ID: 420717



Photo 3 – Heater Treater – Weeds

Photo 4 – Tank Battery – Weeds

Inspection Photos
Location Name: Cass 11-9H
Location ID: 420717



Photo 5 – Tank Battery Signs

Photo 6 – Tank Battery – Weeds

Inspection Photos
Location Name: Cass 11-9H
Location ID: 420717



Photo 7 – Weeds

Photo 6 – Pumping Unit – Weeds

Inspection Photos
Location Name: Cass 11-9H
Location ID: 420717



Photo 9 – Stained Soil Spots at Wellhead

Photo 10 – Stained Soil at Wellhead

Inspection Photos
Location Name: Cass 11-9H
Location ID: 420717



Colorado Oil and Gas Conservation Commission
40.59507, -104.33469, 4767.3ft, 218°
09/27/2022 12:34:32

Photo 11 – Stained Soil at Pumping Unit