

Inspection Photos
Location Name: Cass 11-25H
Location ID: 420020



Photo 1 – Generator – Weeds



Photo 2 – Pumping Unit – Weeds

Inspection Photos
Location Name: Cass 11-25H
Location ID: 420020



Photo 3 – Wellhead – Weeds and Stained Soil



Photo 4 – ECD and Gas Meter – Weeds

Inspection Photos
Location Name: Cass 11-25H
Location ID: 420020



Photo 5 – Secondary Containment



Photo 6 – Secondary Containment – Weildlife Netting is missing

Inspection Photos
Location Name: Cass 11-25H
Location ID: 420020



Photo 7 – Heater Treater – Weeds



Photo 6 – Tank Battery – Weeds

Inspection Photos
Location Name: Cass 11-25H
Location ID: 420020



Photo 9 – Tank Battery Signs

Photo 10 – Weeds in the Interim Reclamation Area

Inspection Photos
Location Name: Cass 11-25H
Location ID: 420020



Photo 11 – Weeds in the Interim Reclamation Area

Photo 12 – Weeds in the Interim Reclamation Area

Inspection Photos
Location Name: Cass 11-25H
Location ID: 420020



Photo 13 – Weeds in the Interim Reclamation Area