

Inspection Photos

API: 071-06631

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/4/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06631 | Date: 10/4/2022

Inspection Photos



Photo 1. Facing north toward the beginning of the access road. There is erosion along the road side that needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06631 | Date: 10/4/2022

Inspection Photos



Photo 2. Facing northwest along the access road to the well site. There is erosion occurring down the road and rock check dams have filled in with sediment



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06631 | Date: 10/4/2022

Inspection Photos



Photo 3. Facing back southwest along the access road to the well site. There is erosion occurring down the road and rock check dams have filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06631 | Date: 10/4/2022

Inspection Photos



Photo 4. Facing southeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06631 | Date: 10/4/2022