

Inspection Photos

API: 071-06672

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/4/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06672 | Date: 10/4/2022

Inspection Photos



Photo 1. Facing northeast along the access road. There is erosion occurring across the road in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06672 | Date: 10/4/2022

Inspection Photos



Photo 2. Facing northeast along the access road to the well site. The check dams have filled in with sediment causing stormwater to flow around onto the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06672 | Date: 10/4/2022

Inspection Photos



Photo 3. Facing east toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06672 | Date: 10/4/2022