

Inspection Photos
Location Name: UPRR 43 Pan AM I #13
Location ID: 318382



Photo 1 tracking pad



Photo 2 loc pic weeds around equipment and location.

Inspection Photos
Location Name: UPRR 43 Pan AM I #13
Location ID: 318382



Photo 3 weeds around equipment




Photo 4 sign faded not legible. Weeds