

Inspection Photos
Location Name: North Platte K21-O24-34HC
API #05-123-41885




Photo #1 well



Inspection Photos
Location Name: North Platte K21-O24-34HC
API #05-123-41885



Photo #2 Stained Soil



Photo #3 Mechanical Conditions