

Inspection Photos
Location Name: North Platte K21-O24-34HNC
API #05-123-41886



Photo #1 well

Inspection Photos
Location Name: North Platte K21-O24-34HNC
API #05-123-41886



Photo #2 Stained Soil



Photo #3 Mechanical Conditions