

Inspection Photos
Location Name: North Platte K31-O34-34HNB
API #05-123-41887



Photo #1 well



Inspection Photos
Location Name: North Platte K31-O34-34HNB
API #05-123-41887



Photo #2 Stained Soil



Photo #3 Mechanical Conditions