

Inspection Photos
Location Name: Federal 26-1
Location ID: 320848



IMG 01
Well sign




IMG 02
Location overview



04Oct22 13:15 Ad-hoc
Pagosa Springs CO 81121, United States © 04-Oct-22 13:15:08

IMG 03

Gas bubbles at wellhead



04Oct22 13:15 Ad-hoc
Pagosa Springs CO 81121, United States © 04-Oct-22 13:15:08

IMG 04

Gas bubbles at wellhead



IMG 05

Ditch filled with sediment, requires post event BMP maintenance



IMG 06

Erosion off of access road




IMG 07

Culvert filled with sediment, requires post event BMP maintenance



IMG 08

Erosion off of access road




IMG 09

Erosion off of access road



IMG 10

Ditch filled with sediment, requires post event BMP maintenance



IMG 11
Erosion off of access road




IMG 12
Erosion channel off of access road



IMG 13

Sediment on access road, ditch requires post event BMP maintenance



IMG 14

Erosion off of access road



IMG 15

Sediment on access road, culvert inlet is buried, requires post event BMP maintenance



IMG 16

Erosion near culverts



IMG 17

Erosion near culvert, . Culvert outlet is unprotected



IMG 18

Sediment on access road, ditch requires post event BMP maintenance



IMG 19
Culvert Inlet is buried



IMG 20
Culvert with no outlet protection