

# Inspection Photos

September 28, 2022

Operator: Argali Exploration Company - #3975

Location ID: 313240

Location Name: Zschach State-68N90W /24NWNE

Inspection Document #: 702800768

Moffat County, CO

NWNE Section 24 T8N R90W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Zschach State-68N90W /24NWNE  
Location ID: 313240



**Photo 1.** Photo taken from the north shows an overview of the Location.



Inspection Photos  
Location Name: Zschach State-68N90W /24NWNE  
Location ID: 313240



**Photo 2.** Photo shows a peeling tank label.



**Photo 3.** Photo shows the tank with a peeling label.

## Inspection Photos

Location Name: Zschach State-68N90W /24NWNE

Location ID: 313240



**Photo 4.** Photo shows the wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800768



Inspection Photos  
Location Name: Zschach State-68N90W /24NWNE  
Location ID: 313240



**Photo 5.** Photo shows an anchor marker in disrepair.



**Photo 6.** Photo shows an unmarked anchor.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800768



Inspection Photos  
Location Name: Zschach State-68N90W /24NWNE  
Location ID: 313240



**Photo 7.** Photo shows interim areas vegetated with perennial grasses.



**Photo 8.** Photo shows interim areas vegetated with perennial grasses.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800768