

Construction and Stormwater Inspection

September 23, 2022

Operator: NOBLE ENERGY INC- #100322

Location ID: 460265

Inspection Document #: 697504234

Weld County, CO

NWNE Section 31 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name:CC31-02 /Pad
Location ID: 460265



Photo 1. Photo taken from the east entrance of location, facing Southwest. Photo illustrates drilling operations are underway.



Photo 2. Photo taken from the northeastern location, facing West. Photo illustrates stormwater erosion repairs have been completed.

Inspection Photos
Location Name:CC31-02 /Pad
Location ID: 460265



Photo 3. Photo taken from the northwestern location, facing South. See comments under Photo 2.



Photo 4. Photo taken from the northwestern location, facing North. See comments under Photo 2.

Inspection Photos
Location Name:CC31-02 /Pad
Location ID: 460265



Photo 5. Photo taken from the northwestern location, facing Northeast. See comments under Photo 2.



Photo 6. Photo taken from the western location, facing South. See comments under Photo 2.

Inspection Photos
Location Name:CC31-02 /Pad
Location ID: 460265



Photo 7. Photo taken from the southwestern location, facing East. Photo illustrates Operator has responded to the previous corrective action to comply with Rule 1002.c.



Photo 8. Photo taken from the southeastern location, facing Northeast. See comments under Photo 2.