

Construction and Stormwater Inspection

September 23, 2022

Operator: NOBLE ENERGY INC- #100322

Location ID: 459852

Inspection Document #: 697504245

Weld County, CO

NWNE Section 8 T3N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DD08-02 /Pad
Location ID: 459852



Photo 1. Photo taken from the northern location, facing West. Photo illustrates stormwater erosion repairs have been completed.



Photo 2. Photo taken from the northern location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: DD08-02 /Pad
Location ID: 459852



Photo 3. Photo taken from the northeastern location, facing East. See comments under Photo 1.



Photo 4. Photo taken from the northeastern location, facing Northeast. See comments under Photo 1.

Inspection Photos
Location Name: DD08-02 /Pad
Location ID: 459852



Photo 5. Photo taken from the northeastern location, facing South. See comments under Photo 1.



Photo 6. Photo taken from the northeastern location, facing Southwest. See comments under Photo 1.

Inspection Photos
Location Name: DD08-02 /Pad
Location ID: 459852



Photo 7. Photo taken from the southeastern location, facing Southeast. See comments under Photo 1.



Photo 8. Photo taken from the southeastern location, facing West. See comments under Photo 1.