

Final Reclamation Inspection

September 28, 2022

Operator: HIGHPOINT ENERGY LLC - 10544

Location ID: 418750

Inspection Document #: 697504247

Weld County, CO

SESW Section 15 T6N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Photo 1. Google Earth aerial imagery from 4/7/2010 prior to oil and gas operations. Photo illustrates the parcel and location were associated with other land disturbances. The red polygon is the approximate footprint of the RBF/15B location.

Inspection Photos
Location Name: RBF /15B
Location ID: 418750



Photo 2. Google Earth aerial imagery from 6/11/2021 post plugging operations. Photo illustrates the parcel and location are still associated with other land disturbances. The red polygon is the approximate footprint of the RBF/15B location.



Figure 4: RBF 15B LOOKING WEST (SE1/4 SW1/4 SEC15 T6N R67W, 4-16-10)

Photo 3. Location Picture submitted as part of the permitting process. Photo illustrates the vegetation appears to consist of weedy, annual vegetation.



Inspection Photos
Location Name: RBF /15B
Location ID: 418750



Photo 4. Photo taken from the access road entrance, facing South. Photo illustrates other land disturbance activities are evident and continue.



Photo 5. Photo taken from the access road entrance, facing West. See comments under Photo 4.

Inspection Photos
Location Name: RBF /15B
Location ID: 418750



Photo 6. Photo taken from a portion of the location. Photo illustrates a List B Colorado noxious weed, Canada thistle.



Photo 7. Photo taken from the southeastern berm, facing North. Photo illustrates Canada thistle growth throughout the berm which was observed throughout other portions of the berm to the north and west.

Inspection Photos
Location Name: RBF /15B
Location ID: 418750



Photo 8. Photo taken from the northeastern berm, facing West. See comments under Photo 7.



Photo 9. Photo taken from the northern berm, facing West. See comments under Photo 7.

Inspection Photos
Location Name: RBF /15B
Location ID: 418750




Photo 10. Photo taken from the southern location, facing North. See comments under Photo 7.



Photo 11. Reference photo taken west of the location, facing West. See comments under Photo 2.



Photo 12. Photo taken from location illustrates not all debris has been removed.