

Inspection Photos
Location Name: Wilson 29-20
Location ID: 415293



Photo 1 – Wellhead



Photo 2 – Pumping Unit

Inspection Photos
Location Name: Wilson 29-20
Location ID: 415293



Photo 3 – Weeds growing in the Interim Reclamation Area



Photo 4 – Weeds growing in the Interim Reclamation Area

Inspection Photos
Location Name: Wilson 29-20
Location ID: 415293



Photo 5 – Weeds growing in the Interim Reclamation Area



Photo 6 – Weeds growing in the Interim Reclamation Area