

Inspection Photos
Location Name: Silverback 36-A PAD
Location ID: 443555



Photo 1 – Wellheads



Photo 2 – Tank Battery

Inspection Photos
Location Name: Silverback 36-A PAD
Location ID: 443555



Photo 3 – Tank Battery Sign

Photo 4 – Labels had faded no longer visible

Inspection Photos
Location Name: Silverback 36-A PAD
Location ID: 443555



Colorado Oil and Gas Conservation Commission
40.97276, -104.27259, 5201.0ft, 150°
09/28/2022 13:15:07

Photo 5 – Maintenance Tank – NFPA Label



Colorado Oil and Gas Conservation Commission
40.9728, -104.27191, 5210.5ft, 237°
09/28/2022 13:15:49

Photo 6 – ECDs

Inspection Photos
Location Name: Silverback 36-A PAD
Location ID: 443555



Photo 7 – Separators



Photo 8 – Flare

Inspection Photos
Location Name: Silverback 36-A PAD
Location ID: 443555



Photo 9 – Netting in disrepair



Photo 10 – Stained Soil

Inspection Photos
Location Name: Silverback 36-A PAD
Location ID: 443555



Photo 11 – Stained Soil at Compressor



Photo 12 – Oil Waste in Containment and Netting in disrepair

Inspection Photos
Location Name: Silverback 36-A PAD
Location ID: 443555



Photo 13 – Netting in disrepair



Photo 14 – Stained Soil