

Final Reclamation Inspection

September 28, 2022

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 323392

Inspection Document #: 697504255

Weld County, CO

NESW Section 27 T8N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PIERCE UNIT-KENNEDY #3
Location ID: 323392



Photo 1. Photo taken from the location, facing South. Photo illustrates not all equipment has been removed.



Photo 2. Photo taken from location, facing East. It is unclear whether this was used for oil and gas operations. If it was, it shall be removed per Rule 1004.a.

Inspection Photos
Location Name: PIERCE UNIT-KENNEDY #3
Location ID: 323392



Photo 3. Photo taken from the western location, facing South. Photo illustrates final reclamation activities have not been completed.



Photo 4. Photo taken from the western location, facing North. See comments under Photo 3.